HIGH-LEVEL TACTILE **INSPECTIONS**

SAMPLING PHASE 1 REPORT Tantallon Castle PIC164



HISTORIC | ÀRAINNEACHD ENVIRONMENT | EACHDRAIDHEIL SCOTLAND | ALBA

Title:	High-Level Tactile Sample Inspection Project Phase 1 Report PIC164 Tantallon Castle
Authors:	
Document created:	August 2021
Reviewed by:	
Date reviewed:	17/09/2021
Approved by:	
Date of Approval:	17/09/2021
Version Number:	V0100

Version Control

Version	Date	Status	Prepared by	Amendments
V0001	19/08/2021	Draft		First draft
V0100	17/09/2021	Approved		Approved

HLTI Sampling: Report - Introduction



PIC ID # ↓	PIC164	Site na	me	Tantallon Castle	е		
Inspection start	09/08/2021	Inspect	ion end	11/08/2021		Submission	17/09/2021
Lead HBFA							
Sample Inspectors							

Introduction:

As a result of findings on the first four full site High Level Tactile Inspections, SMT endorsed an accelerated programme that will see high-level tactile sample inspection carried out initially to 16 sites identified as having a high risk potential. Sample inspection for Tantallon Castle was carried out in accordance with HES Management of Risk Procedures as set out in High-level Fabric Policy and High level Tactile Inspection Procedures.

The Sample Inspection Report only reports on high level fabric risks within pre-determined areas and does not provide any assessment of risk in other areas on site.

Tactile inspections of five sample areas (Kitchen Range/Leigh Hall (A), Gatehouse and Foretower (B), remaining Stack of masonry at the North end of the Kitchen Range (C), the Outer Gate (D) and the Doocot (E) were completed from an alloy tower or using rope access/steeple jack teams (observed with GoPro Cameras).

HLF Inspection Risk Matrix:

HES-T1C-HLF-RAS-X-X-V0200-RiskMatrix

C	onsequence	1	2	3	4	5
Prob	ability	No Injury	Minor injury	Moderate injury	Major injury	Fatal or life-altering injury
5	Fabric fall almost certain	5	10	15	20	25
4	Fabric fall highly likely	4	8	12	16	20
3	Fabric fall likely	3	6	9	12	15
2	Fabric fall unlikely	2	4	6	8	10
1	Fabric fall highly unlikely	1	2	3	4	5

RISK RATING	RISK SCORE RANGE
High	15-25
Medium	10- 14
Low	1-9

HLTI Sample Areas:


HLTI Sampling: Report - Introduction



Area:	Colour:	Sample Area Name:
Α		Kitchen Range
В		Gatehouse
С		Stack
D		Outer Entrance
Е		Doocot



Click on link to open drawing in PDF viewer: PIC164-SKE-V3-SampleAreas.pdf



HLTI Sampling: Report - Summary dashboard



PIC ID# PIC164	Submission	17/09/2021		
Select Sample area of which data displayed ↓	a should be	All areas	Number of observations	40
Identified Risk	High 20	Mediu 10	Low 10	
Residual Risk	High O	Mediu	Low 31	

Insr	nection	Action:
1112	Jection	Action.

Class V Report = Fabric detached during tactile inspection	Access Restriction = Risk of fabric falling and causing harm Monitor Observat				
	High = Full site closure	Medium = Partial site closure	Low = Minor access restriction	Plan Repairs = No immediate action	
16	0	6	0	18	

Inspection types:	Tactile	40	Visual	0
-------------------	---------	----	--------	---


Key comments:


Tantallon castle is predominantly constructed from a mixture of sandstone and poorly compacted breccia. Within the inspected areas these were found to be soft and susceptible to erosion. The sandstone also suffers surface scaling and delamination along bedding planes while the breccia tends to be friable and prone to crumbling. Localised decay and failure of the pointing mortar has caused some to become detached, often also resulting in the loosening of pinning stones.

Loose fragments of sufficient height and/or size to cause severe injury or death to people below were found inside the gatehouse. The risk of injury or death is heightened as all visitors to the castle have to pass through the restricted space below to enter the castle. Of particular risk are the arch voussoirs of the southern upper window where two sizeable fragments detached during inspection. Further voussoirs are cracked and an associated structural crack runs through the window to the wall head. Sizeable areas of surface delamination were observed on the stepped gable skews of the doocot and the harling was found to be boss in many areas on this structure. No high risk areas remain outstanding inside the Kitchen Range/Leigh Hall or the stack at the North end of the Kitchen range nor on the outer gate adjacent to the visitor path.




Click on link below image to open Interactive PDF in PDF viewer. In PDF viewer, the drawing is an interactive PDF, click on the labels to open the relevant OBS form for further information.









PIC164-HLR-SI-B-IntS.pdf

